

30 September 1981

MEMORANDUM FOR: Director of Data Processing

ATTENTION: Executive Officer

STAT FROM: [REDACTED]
Deputy Director for Processing

SUBJECT: Processing Weekly Report for Week
Ending 29 September 1981

1. Systems Availability: Attached is the Systems Availability Report.

STAT 2. The [REDACTED] had a good week. The longest outages occurred outside the prime shift. Early Wednesday, GIMPROD lost 40 minutes due to an apparent problem with an IBM disk controller, but no hardware problem was isolated. Seventy-two minutes was lost by JES and Batch on Friday night due to hardware problems which arose after some equipment changes. Saturday afternoon, JES and Batch lost about two hours each due to a bad chip in a Telex disk controller. [REDACTED]

STAT 3. In the Special Center, CAMPROD had eight unscheduled interruptions this week; the most serious problem arose on Monday, when an IBM terminal controller failed, for a loss of 79 minutes. More than an hour was lost Wednesday and Thursday due to CAMS software. On Thursday, DDOSTAR, DDONIPS, and DDOGIMS all were halted for about an hour each when an Amdahl 470/V6 hung on a Telex disk pack holding the system software. [REDACTED]

STAT 4. MPS - We met with Commo and Applications to review system integrity problems. Several actions are underway, including an end-to-end check from CDS, to get a handle on our problems. [REDACTED]

STAT 5. MPS - We ran a test of printing OER traffic in the OCO operations center. This test was to determine the impact on OCO of moving the OER printers to [REDACTED] to support USSR. [REDACTED]

STAT

STAT

STAT
STAT

6. [redacted] of SPD and [redacted] briefed the CAMS 2 [redacted] contractors on VM, AIM and GIM II. Follow-up meetings are planned for the purpose of clarifying issues related to GFE Software. [redacted]

STAT
STAT

7. CEMB/ED installed channel to channel adapters from the IBM 3033-MP to the IBM 370/168-2 and 168-3 on Friday, 25 September. These installs were implemented to support networking. [redacted]

STAT

8. Delivery and installation of the first Burroughs equipment began on Tuesday, 29 September. [redacted]

STAT

9. TP/ED installed and tested a new switching device on the CAMS (VM backup) printer [redacted] on Wednesday, 23 September. This switching device allows the CAMS printer to be used as a hardware backup to the existing VM printer. [redacted]

STAT
STAT

10. OD has received approval from OS for the installation of Secure Access Control System (SACS) Terminal in the Safe Computer Center. In addition, necessary modifications have been made to accommodate the addition of an 'S' indicator to the badge. An authorized access list for indicators will be furnished to the Office of Security. [redacted]

STAT

11. The following is an update on the water leak problem that occurred in the Special Center Tape Library on 16 September.

- o All wet tapes were dried by hand according to the procedures for handling water tapes.
- o Dry tapes that were removed but did not suffer water damage were returned to the library after 24 hours.
- o Wet tape racks were dried and left vacant for 24 hours.
- o Tapes that were in scratch status prior to the damage were replaced.
- o A memorandum was sent to the users along with a list of their tapes asking if the suspect tapes could be categorized as scratch immediate need or hold immediate attention unnecessary. Two hundred and fifty tapes were replaced with the user assistance.
- o All self loaders and numbers have been put back on all the remaining suspect tapes. These tapes will continue to be isolated

from the library. They are stored in numeric order outside the tape library within the center. These tapes now number less than 400.

- o Any tape that is of immediate need has been set aside to be certified. If the tape is without error the user is notified to set up a tape copy.
- o The scratch list is checked each day. Should any of the damaged tapes in hold appear on the list it is replaced with a new tape and returned to the library.

No major problems have surfaced since the occurrence of the water problems. OD continues to look into safeguards such as tape rack canopies or plastic covers to circumvent problems should another water leak occur. [redacted]

STAT

STAT

Att: a/s



STAT

P.S. [redacted] was transferred to CSS from OD for a two year rotation, he will be assigned to the Systems Administrative Group. [redacted]

STAT

UNCLASSIFIED

30 SEPTEMBER 1981

DDA/ODP
SYSTEMS AVAILABILITY SUMMARY
MONDAY 21 SEP 1981 THRU SUNDAY 27 SEP 1981

SYSTEM	CURRENT WEEK 21 SEP - 27 SEP	PREVIOUS 90 DAYS 21 JUN - 21 SEP	DIFFERENCE
BATCH	95.39	97.95	- 2.56
INTERACTIVE	99.28	98.64	+ .64
GIMS	96.67	97.61	- .94
CAMS	98.93	96.93	+ 2.00
OCR-COLTS	98.74	95.87	+ 2.87
OCR-RECON	98.74	95.23	+ 3.51
DDO-STAR	96.69	97.43	- .74
OSWR-TADS	99.95	98.29	+ 1.29

ALL systems, with the exception of BATCH, reported above the goal of 96 percent for the week. BATCH experienced 4 hours and 37 minutes of hardware problems, a 2 hour and 30 minute power outage (VEPCO) and 33 minutes lost due to software errors.